


NOTES:

1. THE HANDLE/STEM REPAIR KIT FOR THIS MODEL IS: 5851LFHST.
2. THE VALVE REPAIR KIT FOR THIS MODEL IS: 5800VRKT.



Haws[®]

1455 KLEPPE LANE
SPARKS, NEVADA, 89431
(775) 369-4712 FAX (765) 369-7424
E-MAIL: HAWS@HAWSCO.COM
WEBSITE: WWW.HAWSCO.COM

MODEL(S) 5851LF

ECN NO. REVISED PER BY: HM
ECN: 4754
DRAWN: GE DATE: 1/19/95
APPROVED: [Signature]

PART NUMBER 0002077550
DRAWING NO. 11884A00
REV. 6

SCALE: 1:1 DRAWING TYPE: INSTALLATION SIZE: A SHEET 1 OF 1