





* THESE DIMENSIONS ARE FOR STANDARD UNITS. FOR
FREEZE RESISTANT FOUNTAINS PLEASE REFER TO THE
INSTRUCTIONS SUPPLIED WITH THE UNIT.



CAUTION

REGARDING CONCRETE/MASONRY WALL MOUNTING:
DO NOT SECURE MOUNTING PLATE TO SAME SIDE OF WALL AS FOUNTAIN.
AVOID COMPROMISING INTEGRITY OF WALL WHEN ANCHORING FOUNTAIN.
IT IS RECOMMENDED THAT INSTALLER CALL TECHNICAL SUPPORT IF THERE
ARE ANY QUESTIONS AS TO HOW TO OBTAIN A PROPER ANCHOR IN
CONCRETE/MASONRY WALLS. 1-800-766-5612



HAWS
corporation

INFO FAX : 1-888-FAX-HAWS (1-888-329-4297)
1455 Kiege Ln, Sports NY, 89431
Phone: 775-359-4712 Fax: 775-359-7424
Haws 74 Bochweg 3 CH-3401 Burgdorf Switzerland
Haws Mfg Pte Ltd 74 Sungai Kodut Loop Singapore 729531
e-mail: Haws@hawsco.com Website: www.hawsco.com

TECH. NO. 10838C0017
DRAWN: 6710
DATE: 6/93
CHECKED: 10838C00
DATE: 6/93
APPROVED: 10838C00
SCALE: 1/8" = 1"

MODEL(S):
INFO FAX DOC # 26710
DRAWING TYPE: INSTALLATION/BACKPACK
SIZE: A 1 of 1